


C-more Remote Access Procedure

- 1) Download the file attachment from email.
- 2) The file extension is .pdf, change it to .exe and click OK on the warning that changing file extensions can cause problems.
- 3) The file name sets the IP address and port to connect to. Do not change the formatting of anything after the " _ "
- 4) Change 000.000.000.000 to the IP address of the HMI on your network.
- 5) Leave the port set to 11102 unless you have multiple installed machines.



- 6) Double-click the icon to open the C-more Console program. You will be prompted for the login information provided with your Power+.



- 7) The C-more Console works just like the touch screen on the Power+. Click on a button to activate it.

